

City of San Diego Test Results

Initial Contaminant Results

SAMPLE_DATE	LOCATION	ANALYTE	VALUE	UNITS
2/23/2017	Charter School Hose Bib Room 138	VINYL_CHLORIDE	ND	UG/L
2/23/2017	Backflow Preventer (North side). 36th St	VINYL_CHLORIDE	ND	UG/L
2/23/2017	Health Office Sink, Cold	VINYL_CHLORIDE	ND	UG/L
2/23/2017	Health Office Sink,Hot	VINYL_CHLORIDE	ND	UG/L
2/23/2017	Drinking Ftn. 100 building	VINYL_CHLORIDE	ND	UG/L
2/23/2017	BackFlow Preventer (East side) National Ave	VINYL_CHLORIDE	ND	UG/L
2/23/2017	Hose Bib Room 103	VINYL_CHLORIDE	ND	UG/L
2/23/2017	Charter School Sink DF Room 127	VINYL_CHLORIDE	1.9	UG/L
2/23/2017	Charter School Sink Faucet Room 128	VINYL_CHLORIDE	1.79	UG/L
3/3/2017	Charter School Sink Faucet Room 128	VINYL_CHLORIDE	2.35	UG/L
3/3/2017	Charter School Sink DF Room 127	VINYL_CHLORIDE	2.32	UG/L

Follow-Up Testing Revealed No Further Contamination

SAMPLE_DATE	LOCATION	ANALYTE	VALUE	UNITS
3/10/2017	Charter School Sink DF Room 127	VINYL_CHLORIDE	ND	UG/L
3/10/2017	Room 124 Faucet	VINYL_CHLORIDE	ND	UG/L
3/10/2017	Room 130 Faucet	VINYL_CHLORIDE	ND	UG/L
3/10/2017	Backflow Preventer (South side) 36th St	VINYL_CHLORIDE	ND	UG/L
3/10/2017	Charter School Sink Faucet Room 128	VINYL_CHLORIDE	ND	UG/L

ND – Not Detected